EVALUATION OF WATER DAMAGED EQUIPMENT

EH020 & REM025 MODEL WASHER-EXTRACTORS

Has Your Laundry Flooded? Can Your Laundry Equipment Be Saved with Replacement Parts?

If your laundry has flooded, please refer to graphic below for assistance on parts replacement for your washer or dryer.

In many cases, depending on the water level, repairs may involve parts replacement only, not entire machines. Please be advised that these tips only apply to specific Continental laundry machinery.

The objective of this bulletin is to help identify potential component damage/ replacement due to exposure to water. This is only a guide and does not guarantee the restoration of functionality or the future durability of equipment.

Contact the Skyline Equipment service department at 800-444-1227 for service help!

For more Hurricane Harvey disaster relief help, visit www.cgilaundry.com/disaster-relief.html.

36"+
Control Panel, Relays & Boards, Water Valves, Wiring Harness

24"- 36"
Door Lock, Tub Bearings, Balance Switch

12"- 14"
Drain Valve, Motor Ground Switch, Inverter, Motor

EH020 **REM025**

Customer Name _____

Phone Number _____

Email _____

Model# _____

Serial Number _____

www.cgilaundry.com • 800-256-1073
2500 State Road 44 • Oshkosh, WI 54904 • 920-231-8222 • Fax 920-231-4666

CONTINENTAL GIRBAU INC.®

Continental Girbau Inc. 09/17

EVALUATION OF WATER DAMAGED EQUIPMENT

EH030, EH040 & EH060 MODEL WASHER-EXTRACTORS

Has Your Laundry Flooded? Can Your Laundry Equipment Be Saved with Replacement Parts?

If your laundry has flooded, please refer to graphic below for assistance on parts replacement for your washer or dryer.

In many cases, depending on the water level, repairs may involve parts replacement only, not entire machines. Please be advised that these tips only apply to specific Continental laundry machinery.

The objective of this bulletin is to help identify potential component damage/ replacement due to exposure to water. This is only a guide and does not guarantee the restoration of functionality or the future durability of equipment.

Contact the Skyline Equipment service department at 800-444-1227 for service help!

For more Hurricane Harvey disaster relief help, visit www.cgilaundry.com/disaster-relief.html.

42"+
Control Panel, Relays & Boards, Water Valves, Wiring Harness, Inverter

34"- 38"
Door Lock, Tub Bearings

24"- 36"
Motor, Balance Switch

12"- 14"
Drain valve, Motor Ground Switch

EH030 **EH040**

42"+
Control Panel, Relays & Boards, Water Valves, Wiring Harness

34"- 38"
Door Lock, Tub Bearings, Balance Switch

24"- 36"
Motor, Motor Ground Switch, Inverter

12"- 14"
Drain valve

EH060

Customer Name _____
Phone Number _____
Email _____
Model# _____
Serial Number _____

www.cgilaundry.com • 800-256-1073
2500 State Road 44 • Oshkosh, WI 54904 • 920-231-8222 • Fax 920-231-4666

CONTINENTAL GIRBAU INC.®

Continental Girbau Inc. 09/17

EVALUATION OF WATER DAMAGED EQUIPMENT

RMG033, RMG040, RMG055 & RMG070 MODEL WASHER-EXTRACTORS

Has Your Laundry Flooded? Can Your Laundry Equipment Be Saved with Replacement Parts?

If your laundry has flooded, please refer to graphic below for assistance on parts replacement for your washer or dryer.

In many cases, depending on the water level, repairs may involve parts replacement only, not entire machines. Please be advised that these tips only apply to specific Continental laundry machinery.

The objective of this bulletin is to help identify potential component damage/ replacement due to exposure to water. This is only a guide and does not guarantee the restoration of functionality or the future durability of equipment.

Contact the Skyline Equipment service department at 800-444-1227 for service help!

For more Hurricane Harvey disaster relief help, visit www.cgilaundry.com/disaster-relief.html.

Customer Name _____

Phone Number _____

Email _____

Model# _____

Serial Number _____

www.cgilaundry.com • 800-256-1073

2500 State Road 44 • Oshkosh, WI 54904 • 920-231-8222 • Fax 920-231-4666

CONTINENTAL GIRBAU INC.®

Continental Girbau Inc. 09/17

EVALUATION OF WATER DAMAGED EQUIPMENT

L1030, L1040 & L1050 MODEL WASHER-EXTRACTORS

Has Your Laundry Flooded? Can Your Laundry Equipment Be Saved with Replacement Parts?

If your laundry has flooded, please refer to graphic below for assistance on parts replacement for your washer or dryer.

In many cases, depending on the water level, repairs may involve parts replacement only, not entire machines. Please be advised that these tips only apply to specific Continental laundry machinery.

The objective of this bulletin is to help identify potential component damage/ replacement due to exposure to water. This is only a guide and does not guarantee the restoration of functionality or the future durability of equipment.

Contact the Skyline Equipment service department at 800-444-1227 for service help!

For more Hurricane Harvey disaster relief help, visit www.cgilaundry.com/disaster-relief.html.

L1030 L1040 L1050

Customer Name _____

Phone Number _____

Email _____

Model# _____

Serial Number _____

www.cgilaundry.com • 800-256-1073

2500 State Road 44 • Oshkosh, WI 54904 • 920-231-8222 • Fax 920-231-4666

CONTINENTAL GIRBAU INC.®

Continental Girbau Inc. 09/17

EVALUATION OF WATER DAMAGED EQUIPMENT

GCW/GDP MODEL LIGHT COMMERCIAL EQUIPMENT

Has Your Laundry Flooded? Can Your Laundry Equipment Be Saved with Replacement Parts?

If your laundry has flooded, please refer to graphic below for assistance on parts replacement for your washer or dryer.

In many cases, depending on the water level, repairs may involve parts replacement only, not entire machines. Please be advised that these tips only apply to specific Continental laundry machinery.

The objective of this bulletin is to help identify potential component damage/ replacement due to exposure to water. This is only a guide and does not guarantee the restoration of functionality or the future durability of equipment.

Contact the Skyline Equipment service department at 800-444-1227 for service help!

For more Hurricane Harvey disaster relief help, visit www.cgilaundry.com/disaster-relief.html.

GCW

GCD

Customer Name _____

Phone Number _____

Email _____

Model# _____

Serial Number _____

www.cgilaundry.com • 800-256-1073

2500 State Road 44 • Oshkosh, WI 54904 • 920-231-8222 • Fax 920-231-4666

CONTINENTAL GIRBAU INC.®

Continental Girbau Inc. 09/17

EVALUATION OF WATER DAMAGED EQUIPMENT

KDE/KDG; GWN, JDE/JDG, JSE/JSG MODEL LIGHT COMMERCIAL EQUIPMENT

Has Your Laundry Flooded? Can Your Laundry Equipment Be Saved with Replacement Parts?

If your laundry has flooded, please refer to graphic below for assistance on parts replacement for your washer or dryer.

In many cases, depending on the water level, repairs may involve parts replacement only, not entire machines. Please be advised that these tips only apply to specific Continental laundry machinery.

The objective of this bulletin is to help identify potential component damage/ replacement due to exposure to water. This is only a guide and does not guarantee the restoration of functionality or the future durability of equipment.

Contact the Skyline Equipment service department at 800-444-1227 for service help!

For more Hurricane Harvey disaster relief help, visit www.cgilaundry.com/disaster-relief.html.

36"+
Control Panel, Relays & Boards, Wiring Harness

24"- 36"
Drum, Front & Rear Seals, Door Switch

12"- 14"
Gas Train/Electric Element, Rollers, Motor

KDE/KDG

36"+
Conrtol Panel, Relays & Boards, Wiring Harness, Water Valves

24"- 36"
Transmission

12"- 14"
Brake Assembly, Pump, Motor

GWN

36"+
Control Panel, Relays & Boards, Wiring Harness

24"- 36"
Drum, Front & Rear Seals, Door Switch

12"- 14"
Gas Train/Electric Element, Rollers, Motor

JDE/JDG, JSE/JSG

Customer Name _____
Phone Number _____
Email _____
Model# _____
Serial Number _____

www.cgilaundry.com • 800-256-1073
2500 State Road 44 • Oshkosh, WI 54904 • 920-231-8222 • Fax 920-231-4666

CONTINENTAL GIRBAU INC.®

Continental Girbau Inc. 09/17

EVALUATION OF WATER DAMAGED EQUIPMENT

CG30X2 & CG45X2 MODEL STACK DRYING TUMBLERS

Has Your Laundry Flooded? Can Your Laundry Equipment Be Saved with Replacement Parts?

If your laundry has flooded, please refer to graphic below for assistance on parts replacement for your washer or dryer.

In many cases, depending on the water level, repairs may involve parts replacement only, not entire machines. Please be advised that these tips only apply to specific Continental laundry machinery.

The objective of this bulletin is to help identify potential component damage/ replacement due to exposure to water. This is only a guide and does not guarantee the restoration of functionality or the future durability of equipment.

Contact the Skyline Equipment service department at 800-444-1227 for service help!

For more Hurricane Harvey disaster relief help, visit www.cgilaundry.com/disaster-relief.html.



44”+
Gas Train, Upper Dryer

36”- 38”
Drum, Rear Bearing, Controls, Coin Drop, Air Flow Switch

24”- 36”
Fan Motor, Ignitor, Control Box Wiring, Door Switch, Front & Rear Seals

12”- 14”
Lint Screen, Drive Motor, Drum Rollers, Lint Drawer Switch

CG30X2 **CG45X2**

Customer Name _____
Phone Number _____
Email _____
Model# _____
Serial Number _____

www.cgilaundry.com • 800-256-1073
2500 State Road 44 • Oshkosh, WI 54904 • 920-231-8222 • Fax 920-231-4666

CONTINENTAL GIRBAU INC.®

Continental Girbau Inc. 09/17

EVALUATION OF WATER DAMAGED EQUIPMENT

CG20-30, CG30-40 & CG55-65 MODEL DRYING TUMBLERS

Has Your Laundry Flooded? Can Your Laundry Equipment Be Saved with Replacement Parts?

If your laundry has flooded, please refer to graphic below for assistance on parts replacement for your washer or dryer.

In many cases, depending on the water level, repairs may involve parts replacement only, not entire machines. Please be advised that these tips only apply to specific Continental laundry machinery.

The objective of this bulletin is to help identify potential component damage/ replacement due to exposure to water. This is only a guide and does not guarantee the restoration of functionality or the future durability of equipment.

Contact the Skyline Equipment service department at 800-444-1227 for service help!

For more Hurricane Harvey disaster relief help, visit www.cgilaundry.com/disaster-relief.html.



44"+
Gas Train, Ignitor, Controls, Coin Drop, Control Box Wiring

36"- 38"
Drum, Rear Bearing, Air Flow Switch

24"- 36"
Drive motor, Lint Drawer Switch, Drum Rollers, Door Switch, Front & Rear Seals

12"- 14"
Fan Motor, Lint Screen

CG20-30 **CG30-40** **CG55-65**

Customer Name _____
Phone Number _____
Email _____
Model# _____
Serial Number _____

www.cgilaundry.com • 800-256-1073
2500 State Road 44 • Oshkosh, WI 54904 • 920-231-8222 • Fax 920-231-4666

CONTINENTAL GIRBAU INC.®

Continental Girbau Inc. 09/17

EVALUATION OF WATER DAMAGED EQUIPMENT

CG50-60 & CG75-85 MODEL DRYING TUMBLERS

Has Your Laundry Flooded? Can Your Laundry Equipment Be Saved with Replacement Parts?

If your laundry has flooded, please refer to graphic below for assistance on parts replacement for your washer or dryer.

In many cases, depending on the water level, repairs may involve parts replacement only, not entire machines. Please be advised that these tips only apply to specific Continental laundry machinery.

The objective of this bulletin is to help identify potential component damage/ replacement due to exposure to water. This is only a guide and does not guarantee the restoration of functionality or the future durability of equipment.

Contact the Skyline Equipment service department at 800-444-1227 for service help!

For more Hurricane Harvey disaster relief help, visit www.cgilaundry.com/disaster-relief.html.



CG50-60 CG75-85

Customer Name _____

Phone Number _____

Email _____

Model# _____

Serial Number _____

www.cgilaundry.com • 800-256-1073

2500 State Road 44 • Oshkosh, WI 54904 • 920-231-8222 • Fax 920-231-4666

CONTINENTAL GIRBAU INC.®

Continental Girbau Inc. 09/17

EVALUATION OF WATER DAMAGED EQUIPMENT

CG115-25, CG165-75 & CG195-205 MODEL DRYING TUMBLERS

Has Your Laundry Flooded? Can Your Laundry Equipment Be Saved with Replacement Parts?

If your laundry has flooded, please refer to graphic below for assistance on parts replacement for your washer or dryer.

In many cases, depending on the water level, repairs may involve parts replacement only, not entire machines. Please be advised that these tips only apply to specific Continental laundry machinery.

The objective of this bulletin is to help identify potential component damage/ replacement due to exposure to water. This is only a guide and does not guarantee the restoration of functionality or the future durability of equipment.

Contact the Skyline Equipment service department at 800-444-1227 for service help!

For more Hurricane Harvey disaster relief help, visit www.cgilaundry.com/disaster-relief.html.



44”+
Gas Train, Ignitor, Controls, Control Box Wiring

36”- 38”
Drum, Rear Bearing, Air Flow Switch, Door Switch, Drive Motor

24”- 36”
Lint Drawer Switch, Seals

12”- 14”
Fan Motor, Lint Screen

CG115-25 **CG165-75** **CG195-205**

Customer Name _____
Phone Number _____
Email _____
Model# _____
Serial Number _____

www.cgilaundry.com • 800-256-1073
2500 State Road 44 • Oshkosh, WI 54904 • 920-231-8222 • Fax 920-231-4666

CONTINENTAL GIRBAU INC.®

Continental Girbau Inc. 09/17